

Map of impacted area is attached.
Se adjunta un mapa del área afectada.

News Release

Date: 07-25-2025

Update#2 to Water Situation in Hacienda Neighborhood in Sunland Park

Repairs to a water main break in Sunland Park's Hacienda Neighborhood remain on temporary hold due to the location of the break. In the meantime, water service will be maintained.

The break that occurred on July 25, 2025, is approximately 12 feet below the road surface, which has made standard repair efforts extremely challenging due to the high groundwater table.

Following on-site evaluation, it was determined that dewater operations are required to complete the repair safely and effectively.

Customers will be notified of a timetable for the repair once the logistics have been completed.

For compliance purposes, the Camino Real Regional Utility Authority (CRRUA) has contacted the Office of the State Engineer (OSE) – Las Cruces District Office; New Mexico Department of Finance and Administration (DFA); City of Sunland Park (City Manager's Office); Elephant Butte Irrigation District (EBID); New Mexico Environment Department (NMED); the CRRUA Board of Directors and EPA Region 6 Compliance.

The impacted area is between Boy Scout Lane from Futurity Drive to Frontera Road and San Gabriel Drive from Frontera Road south to Futurity Drive. Adjacent areas also may be affected.

CRRUA appreciates your patience and understanding.

For questions or more information, please contact CRRUA Customer Service 575-332-1076.

-0-

Comunicado de prensa

Fecha: 25-07-2025

Actualización # 2 a Corte de agua en el vecindario de Hacienda en Sunland Park

Las reparaciones de una rotura de la tubería principal de agua en el vecindario Hacienda de Sunland Park permanecen en espera temporal debido a la ubicación de la ruptura. Mientras tanto, se mantendrá el servicio de agua.

La rotura que ocurrió el 25 de julio de 2025 está aproximadamente a 12 pies por debajo de la superficie de la carretera, lo que ha hecho que los esfuerzos de reparación estándar sean extremadamente desafiantes debido al alto nivel freático.

Después de la evaluación in situ, se determinó que se requieren operaciones de desagüe para completar la reparación de manera segura y efectiva.

Los clientes serán notificados de un cronograma para la reparación una vez que se haya completado la logística.

Para fines de cumplimiento, la Autoridad Regional de Servicios Públicos de Camino Real (CRRUA) se ha puesto en contacto con la Oficina del Ingeniero Estatal (OSE) – Oficina del Distrito de Las Cruces; Departamento de Finanzas y Administración de Nuevo México (DFA); Ciudad de Sunland Park (Oficina del Administrador de la Ciudad); Distrito de Riego de Elephant Butte (EBID); Departamento de Medio Ambiente de Nuevo México (NMED); la Junta Directiva de CRRUA y el Cumplimiento de la Región 6 de la EPA.

El área afectada se encuentra entre Boy Scout Lane desde Futurity Drive hasta Frontera Road y San Gabriel Drive desde Frontera Road hacia el sur hasta Futurity Drive. Las áreas adyacentes también pueden verse afectadas.

CRRUA agradece su paciencia y comprensión.

Si tiene preguntas o más información, comuníquese con el Servicio al Cliente de CRRUA al 575-332-1076.